

Annexure D

BUILDING SAFETY CERTIFICATE

No. 684

Dated: 25/08/2025

It is certified that the existing building **St. Mary's High School, Jalna (CBSE) at Survey No. 207, Devalgaon Raja Road, Jalna** is having 04 block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	0 Basement, 1 Ground Floor, and 2 upper floor	0 Basement, 1 Ground Floor, and 1 upper floor	0 Basement, 1 Ground Floor, and 3 upper floor	0 Basement, 1 Ground Floor, and 2 upper floor		

The building is owned/occupied by **St. Mary's High School, Jalna** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **P.W.D. Jalna**..... (Name of Department/Govt.) on **25/08/2025** (date of inspection) in the presence of **prashant Mobite Head clexk**..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **01/04/2025** for a period of **Three**..... years in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on **25/08/2025** at **Jalna** by **R.R. Suryawanshi**

Sub-Divisional Engineer

Signature with Seal: **P.W.D. Sub Division No.3**

Name: **R.R. Suryawanshi**

Designation: **Sub Div. Engineer.**

Name & Address of Department/ Office:

**P.W.D. Sub Division No.3.
Near Durgamata temple
Jalna - 431203**